

FIG. 2




FIG. 3




FIG. 4

Impairment Compensation Configured for Imbalance Characteristics at -2.5 MHz

Image at $+2.5$ MHz is minimum due to configuration of Imbalance Compensation




FIG. 5




FIG. 6







FIG. 8



F/G. 9





F/G. 10





FIG. 11

FIG. 12







FIG. 13

FIG. 14






FIG. 15




FIG. 16




FIG. 17





FIG. 18



F/G. 19